

IOWA DEPARTMENT OF WATER, AIR AND WASTE MANAGEMENT

Report Of Investigation

Page 1 Of 1

<p style="text-align: center;">INVESTIGATION DATE</p> <p>Current 8/30/84 Last 2/29/84</p> <hr/> <p>TO: (Facility Name, Location & Address)</p> <p>Eagle Signal 736 Federal Davenport, IA 52803</p> <p style="text-align: center;">IAD051001337</p> <hr/> <p>RE: (Specify Investigation Purpose Or Cite Rule)</p> <p>RCRA status update in accordance with Work Request #176</p>	<p>FROM: (Use Stamp)</p> <p style="text-align: center;">Region No. 6 P. O. Box 27 Washington, Iowa 52353</p> <hr/> <p>Persons Contacted (Name & Position)</p> <p><u>Arlee D. Tripaldi, Maintenance Supervisor</u></p> <p><u>Richard Erikson, Manufacturing Service Mgr.</u></p>
---	---

OBSERVATIONS/RECOMMENDATIONS

This inspection was conducted to observe closure of storage facilities in accordance with a request for small quantity generator status.

Discussion with Messrs. Tripaldi and Erikson indicated that on 6/19/84, 29 barrels, 6/21/84, 22 barrels, 7/3/84, 29 barrels, and 8/1/84, 26 barrels of hazardous wastes were shipped off-site. As of 8/30/84 less than one barrel of mineral spirits was in storage.

Production is way down at this site. The solid state manufacturing process has been transferred to Texas. Consequently, hazardous wastes possibly generated are also reduced.

Previous storage area was observed with no wastes in storage. Area appeared to have been cleaned as outlined in closure plan details stipulated in 7/27/84 letter from Eder Associates to Barb Cook.

Regarding observation of spilled residues, etc., stains in the asphalt-cement area were definitely noticeable but there was no evidence of residue piles remaining. The stains also appear as though they may have been generated from a variety of other practices other than spillage of hazardous wastes.


 R00307824
 RCRA RECORDS CENTER

RECEIVED
 84 SEP 21 AM 10 51
 DEPARTMENT OF
 WATER, AIR AND WASTE
 MANAGEMENT

SUSPENSE DATE	Signature	Date
<u>11</u>	Inspector Steve Hoambrecker <i>Steve Hoambrecker</i>	9/19/84
	Regional Administrator Merritt W. Van Lier <i>Merritt W. Van Lier</i>	9/20/84
Enclosures (Specify)		
Distribution: Regional Office: Central Office: Inspected Facility: Date copy mailed: 9/20/84 - amw		

IOWA DEPARTMENT OF WATER, AIR AND WASTE MANAGEMENT

WORK REQUEST

P.O. 6

ENTERED 8/13/84 - alin

CPF-00802

REQUEST TO (region or branch): 6	LOCATION OF TASK OR FACILITY EAGLE SIGNAL DAVENPORT	CONTROL NUMBER
REQUESTED BY BARBARA COOK		WORK APPROVAL [Signature]
DATE WORK IS NEEDED 9/15/84		DATE WORK ASSIGNED 2/16/84
ROUTE RESPONSE THROUGH Robert Campbell		DATE WORK RETURNED 5/21/84
DESCRIPTION OF TASK OR REASON FOR REQUEST (attach pertinent documents) This company has requested to be small quantity generator. Attached is the closure plan prepared by EDER ASSOCIATES. THE PLAN INDICATES THAT ALL CLOSURE ACTIVITIES SHOULD BE COMPLETED. PLEASE INSPECT DETERMINE 1) AND REGULATED QUANTITIES OF HW EXIST ON SITE 2) ALL SPILLED RESIDUES HAVE BE CLEANED UP.		
WORK RESULTS Include with previous work request of 2/16/84. # 176		
WORK COMPLETED BY Steve Hoang [Signature]	DATE 9/19/84	SUPERVISOR M.H. 9/21/84

RECEIVED
SEP 21 AM 10:57
IOWA DEPARTMENT OF
WATER, AIR AND WASTE
MANAGEMENT